

SPECIFICATION SHEET

Protective Clothing



KOSTO
BUILT STRONG • BÂTI SOLIDE

FR & Arc Flash Coverall with 4" Reflective tape

VCKF01-VCKF01T

This flame retardant cotton fabric coverall is designed to protect workers exposed to category 2 electric arcs. The fitted waistband with an elastic back and the telescopic pleats at the shoulders allow for better ease of movement. The coverall features numerous pockets for gear and a two-way front zipper with flap. The stand-up collar provides optimal protection.

Certifications

- This garment offers protection for arc flash : (Cat. 2) ATPV 9.2 cal/cm²

Meets the minimum requirements of performance specifications

- NFPA 70E / ASTM F1959 (ASTM F1506)
- NFPA 2112 / ASTM 1930
- CSA Z96-22 - Classe 3, Niveau 2

Fabric

- 100% cotton, flame-retardant and arc flash, (8oz / 270 GMS)
- FR 4" reflective tape
- Preshrunk
- Vat dye

Size:

Regular : 36 to 62
Tall: 36 to 62



High collar with velcro closure

2 radio straps

Two front pockets with flap & Velcro

Two-way metal zipper with flap velcro closure

Slash pocket with access to pant

High resistance aramid FR thread and bar-tacked at all stress points



FR 4" reflective tape

Sleeve pocket for gas detector

Telescopic back for more comfort

Back pocket with Velcro closure

Adjustable cuffs with Velcro

Adjustable leg opening with Velcro



SPECIFICATION SHEET

Protective Clothing



KOSTO
BUILT STRONG • BÂTI SOLIDE

Related Items

VGKF10+VPKF10
FR underwear



VCKF05 / VCKF06
Dazzle Welding
Coveralls



VCKA01
Aluskin
Coverall



Care Guide

Care Instructions

- Protective garments should be cleaned regularly, as per recommended instructions.
- Wash all garments after fixing all closure systems.
- Strictly wash garments inside out.
- Always wash your Flame Retardant PPE separately to avoid some migration of flammable loose fibers or components.
- Please make sure that garments are properly rinsed after wash.
- Do not dry in direct sunlight as this may cause color to fade.
- After cleaning the garment, please inspect before re-use




Wash care instructions

- Wash in 60°C, do not use detergents containing soap & chlorine.
- Do not bleach, or use acids when rinsing.
- Iron at low setting (below 110°C).
- Use dry cleaning agent other than Trichloroethylene.
- Tumble dry allowed.

Size Chart

VCKF01
REGULAR



		Coverall															
			34	36	38	40	42	44	46	48	50	52	54	56	58	60	62
Poitrine	①	po / in	41	43	45	47	49	51	53	55	57	59	61	63	65	67	69
		cm	114	109	114	119	124	129	134	139	144	149	154	160	165	170	175
Longueur	②	po / in	36.5	37.25	38	38.75	39.5	40.25	41	41.5	42	42.5	43	43.5	44	44.5	45
		cm	73	74.5	76	77.5	79	80.5	82	83	84	85	86	87	88	89	90
Jambe	③	po / in	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31
		cm	79	79	79	79	79	79	79	79	79	79	79	79	79	79	79

* Measurements are based on finished garment. * For optimal fit it is recommended to try before purchase

PROTECTION

• RELIABILITY

• VALUE